



A Kabelvorbereitung / Cable preparation

0°

35 mm

Spacer
max. 2 mm

021.2329/021.2331

A Kabelvorbereitung / Cable preparation

90°

40 mm

Spacer
max. 2 mm

021.2328/021.2330

B Kabel einführen / Insert cable

Kabel bis zur angegebenen Position einführen.
Insert cable up to indicated position.

021.2335/021.2402

C1 Kabel ausrichten / Cable orientation

Blaues und braunes Paar positionieren.
Position blue and brown pairs.

Kabelende 1
Cable end 1


Kabelende 2
Cable end 2

021.2332/021.2333




Tool:
R516050

C2 Zugentlastung anbringen / Mount strain relief





Kabelbinder links oder rechts
oben positionieren.

Position cable tie top
left or right.





021.2326/021.2336/023.0278

C3 Kabeleinlass varianten / Cable entry variants





021.2336.1/021.2337.1

D1 Ein Paar kreuzen / Cross over one pair



021.2303/021.2304/021.2334/021.2374

D2 Adern einlegen / Insert wires




023.0275/021.2384/021.2385/023.0276


E Teile ausrichten und zusammen fügen / *Align and mount parts*




F1 Deckel beschalten / *Terminate levers*



Demontage



Demontage



Please note:

This guide shows the best practices for installation **ONLY**. R&M expressly disclaims all liability for any damage to material, equipment, and for any injury or death. Legal health and safety regulations should have priority over best practices as shown in this guide. R&M does not guarantee this guide to be free of errors. Products included may vary from products shown. Please exercise caution.



Headquarters

Switzerland

Reichle & De-Massari AG

Binzstrasse 32

CHE-8620 Wetzikon

Telephone HQ +41 (0)44 933 81 11

Telefax HQ +41 (0)44 930 49 41

E-Mail hq@rdm.com

www.rdm.com

